


SUBMITTAL DATA SHEET

Pump Repair Parts

8300 Series Repair Parts



Model No.	Imp/Dif Kit	Seal Kit	Venturi Kit	Casing
8350	6156-129	6156-133	6156-147	6156-145
8350HP	6156-129	6156-133	6156-151	6156-145
8370	6156-130	6156-133	6156-148	6156-145

Model No.	Imp/Dif Kit	Seal Kit	Venturi Kit	Casing
8310	6156-131	6156-141	6156-149	6156-145
8315	6156-132	6156-141	6156-150	6156-145

*Imp/Dif Kit includes - impeller, diffuser, rotary seal, housing o-ring, seal ring, and diffuser screws

*Seal Kit includes - rotary seal, housing o-ring and seal ring

NO-LEAD: The weighted average of the wetted surface of this no-lead product contacted by consumable water contains less than one quarter of one percent (0.25%) lead.



A.Y. McDonald Mfg. Co.
 P.O. Box 508
 Dubuque, IA 52004-0508

Toll Free: 1-800-292-2737
Fax: 1-800-832-9296
Hours: 7:00 a.m. - 5:00 p.m., CST

sales@aymcdonald.com
 www.aymcdonald.com

A.Y. McDonald considers the information on this assembly drawing correct when published. Item and option availability, including specifications, are subject to change without notice.

Submitted by: