

Isolating Connectors

700PARTD1_

1.6

VISUAL COMFORT & Co.

ARCHITECTURAL COLLECTION

GENERAL PRODUCT INFORMATION:




This product is suitable for indoor dry locations only.

This product is intended to be used with Tech Lighting Kable Lite system only.




1A



- 1 Loosen (Do Not Remove) the six #4-40 set screws with the provided 0.05 Allen wrench to clear the side holes.

1B



- 2 Feed end of one Kable Lite cable half way into the side hole of the isolating connector and tighten the three #4-40 set screws with the 0.05 Allen wrench.
- 3 Feed the other Kable Lite cable half way into the other end of the isolating connector and tighten the three #4-40 set screws with the 0.05 Allen wrench.
- 4 Repeat steps 1 through 3 for the other isolating connector.

SAVE THESE INSTRUCTIONS!